



**THE BOEING COMPANY
SANTA SUSANA FIELD LABORATORY
DISCHARGE MONITORING REPORT
NPDES PERMIT CA0001309**

3rd Quarter 2006 EPA 8 TDQJ 050139 61039

The Boeing Company
Santa Susana Field Laboratory
5800 Woolsey Canyon Road

CERTIFIED MAIL

November 8, 2006

Regional Water Quality Control Board

3rd QUARTER 2006 CORRECTIVE ACTIONS TAKEN

Despite having no surface water monitoring events in the 3rd Quarter of 2006,
Boeing continued to take action to improve surface water discharge quality.

its iterative BMP work plan in accordance with the 2005 13267 response (MWH, 2005). Boeing improved and upgraded multiple BMPs throughout the site in order to address past exceedances and improve surface water discharge quality. Boeing recently provided a summary of recent BMP activities in its first annual SSFL BMP Implementation Report to the Regional Board on October 1, 2006 (MWH, 2006).

Page 3

CERTIFICATION

I certify under penalty of law that this document and all appendices were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel prepared all the data and information reported herein.

Page 4