

APPENDIX F
BORING LOGS AND TRENCH LOGS

Appendix F – Boring Logs and Trench Logs

Table of Contents

Boring Logs – Data Gap Samples

ISRA Area IEL-2	ISRA Area IEL-3	RD-47 Soil Borrow Area
ILBS92B	ILBS0364	ISBS0001
ILBS0146A	ILBS0365	ISBS0002
ILBS0234A	ILBS0366	ISBS0003
ILBS0240A	ILBS0367	ISBS0004
ILBS0294	ILBS0368	ISBS0005
ILBS0295	ILBS0369	ISBS0006
ILBS0296	ILBS0370	ISBS0007
ILBS0297	ILBS0371	ISBS0008
ILBS0298	ILBS0372	ISBS0009
ILBS0326	ILBS0373	ISBS0010
ILBS0327	ILBS0374	
ILBS0328	ILBS0375	
ILBS0329	ILBS0381	
ILBS0330		

Boring Logs - Confirmation Samples

ISRA Area AP/STP-1B	ISRA Area AP/STP-1C-1	ISRA Area AP/STP-1C-2
APET0702	APBS1048A	APET0932
APET0703	APBS1076A	APET0933
APET0704	APBS1088A	APET0922
APET0705	APBS1117A	
APET0706	APBS1128A	
APET0707	APBS1169A	
APET0708	APBS1170A	
APET0709	APBS1172A	
APET0710	APBS1261A	
APET0711	APBS1262A	
APET0712	APET0900	
APET0713	APET0901	
APET0714	APET0902	
APET0715	APET0903	
APET0716	APET0904	
APET0717	APET0905	
APET0718	APET0906	
APET0720	APET0907	
APET0721	APET0908	
APET0722	APET0909	
APET0723	APET0910	
APET0725	APET0911	
APET0726	APET0912	
APET0727	APET0913	
APET0728	APET0914	
APET0729	APET0915	
APET0730	APET0916	
APET0731	APET0917	
APET0732	APET0918	
APET0733	APET0919	
APET0734	APET0920	
APET0737	APET0921	
APET0740	APET0922	
APET0741	APET0923	
APET0742	APET0924	
APET0743	APET0925	
APET0744	APET0926	
APET0745	APET0927	
APET0746	APET0928	
APET0747	APET0929	
	APET0930	
	APET0931	

Boring Logs - Confirmation Samples (continued)

ISRA Area
IEL-2

ISRA Area
IEL-3

ISRA Area
LOX-1B-1

LOX-1B-1t

i

Trench Logs

ISRA Area	Trench ID
AP/STP-1B (East)	APTS0798
AP/STP-1B (West)	APTS0799
AP/STP-1C-1	APTS0999
AP/STP-1C-2	APTS0899
AP/STP-1E-1	APTS0299
AP/STP-1E-3	APTS0399
AP/STP-1E-2	APTS0599
ELV-1C	EVTS0099
ELV-1D	EVTS0199
IEL-2	ILTS0199
IEL-3	ILTS0198
LOX-1B-1	LXTS0099
LOX-1B-2	LXTS0199
LOX-1B-3	LXTS0299

Please contact Art Lenox at 818-466-8795 if you would like to receive a CD containing the Boring Logs and Trench Logs listed in the Appendix F – Boring Logs and Trench Logs, Table of Contents. The logs are not posted on the Boeing External Website due to the large file size.