

APPENDIX E  
BIOASSESSMENT REPORT






Figure 1. Rainfall (inches) measured thru mid-April on SSFL property during the 2010 to 2011 rain year.



Photos taken downstream and upstream of each permitted discharge point from the SSFL property.

